



中国科学院高能物理研究所
Institute of High Energy Physics
Chinese Academy of Sciences



TaichuPix-3 test

Ying ZHANG, XiaoXu Zhang

2023-2-9

Flex test overview


- **Tests of the 2-layer flex with two chips working simultaneously**
 - Config both U10 & U9, analog power changed before&after, digital power do not
- **Test of the 4-layer flex with two chips working simultaneously**



2-layer flex test result

■ FlexV1p3-H: chip U10 & U9


- Config U9/U10 respectively: minimum ITHR is 64 for U9/U10 (no power current overload)
- Config U9 and U10 simultaneously, **minimum ITHR is 128 → noise increased**
- Laser test: U9 and U10 can work simultaneously, NO error code/cross-talk found



4-layer flex test result

■ FlexV1p4-B: chip U10 & U9


- Config U9/U10 respectively: minimum ITHR is 64 for U10, 96 for U9
- Laser test: U9 and U10 can work simultaneously, NO error code/cross-talk found




4-layer flex test result

■ FlexV1p4-C: chip U10 & U9

- Config U9/U10 respectively: minimum ITHR is 64 for U10, 96 for U9
- Laser test: U9 and U10 can work simultaneously, NO error code/cross-talk found



Count efficiency decreasing with ITHR decreasing ??



Status of flex boards

■ Four 4-layer flex bonding with U9 & U10

- One flex short after U9 bonding: FlexV1p4-A → need to be repaired
- Two work normally: FlexV1p4-B, FlexV1p4-C
- One untested: FlexV1p4-D

■ One 2-layer flex bonding with U9 & U10

- Works normally in the beginning, to be problematic during test after plug for several times → damage of socket is under suspicion

■ Eight bare 4-layer flex ready for chip bonding (socket welded)