


Mini TPC at Saclay : update

Boris Tuchming


- Introduction/Reminder
- Recent events
 - Alignment
 - Gas

Goal: test TPC tracking performance in the presence of space charge to check/tune simulation of space charge effect


- Recycle existing chamber present at Saclay
- Use micromegas resistive module as TPC pads
 - Existing detector+electronics (AFTER)+DAQ developed for T2K and ILD R&D
 - New TPC end-plate to plug the micromegas device
- Transparent windows to send UV-rays through the chamber
 - UV rays yield photo-electrons at the cathod level
 - Photo-electrons drift toward micromegas
 - Micromegas amplification yields ion back-flow in drift space
- Measure tracking performance with cosmic muons
 - Trigger with 2 scintillators
 - Use 3 large area micromegas chambers as hodoscope.



- Start steady data acquisition in January 2017
 - Required amount of data for a proper tracking performance study was not known
 - Goal to collect as much data as possible in steady state
 - Typical trigger rate ~ 1 Hz
 - Typical rate for good events in 3 Multigen and TPC volume ~ 0.3 Hz
- Data acquisition in 2017 - 2018
 - Use 95% Argon + 5% Isobutane
 - TPC Mesh at -430 V ($128 \mu\text{m}$ GAP)
 - TPC Drift -10 kV / 48 cm $\rightarrow \sim 200$ V/cm
 - Multigen (v1) anod at $+480$ V
- Issues to be solved before turning UV on
 - Quality:
 - Large e- capture rate in TPC
 - Sometimes poor S/B in multigen
 - Track resolution not as good as expected
 - need to improve tracking
 - Stability
 - Gain in TPC not stable in time
 - S/B in multigen not stable in time
 - Track resolution varying with time



- Quick fit
 - Define track from 2 hits from outermost Multigen (Layer 1 and 3)
 - Compute residuals for the hits in TPC and MG Layer 2
 - Fit (z,x,y) of 3 Multigens
 - Fit 3 rotations relative to (X,Y,Z) axes for TPC
 - Fit drift velocity



Alignment constants are computed regularly




- They should be equal over a short period as we don't move the detectors
- They are not

Reason for instability

- Evidence of degeneracy in fit outputs:
Not enough sensitivity to disentangle a rotation of TPC from a translation of Multigen ?
- Note: this does not track resolution
- This is a problem when you compare an absolute (x,y,z) coordinate between different runs (eg for Tomography)

Recent attempt to improve:

- Fixed two rotations (around z-axis and x-axis)






Layer3x- vs rotation
around Z-axis, in different runs

Alignment resolution

- Use several runs from April data:
- Recompute alignment for every files ~ 1 hr of data taking (~5k trigger)
 - alignment constant (in cm) with floating vs 2 fixed angles



With 2 fixed angles:

- Improve spread from 1.7 cm to ~ 0.2 mm for Layer-3 X-position
- Improve spread from 1.2 cm to 0.2 mm for Layer 3 Z-position
- Also remove tails



Switched to new alignment procedure

- Reprocessed data with new alignment procedure = fixing 2 angles.
- See the expected stability eg for Layer 1, X-position




When TPC bench moved
in the current room

Issue with gas


- Too large absorption in gas (electron capture) affecting resolution.
- Presumably O2 outgasing or leakage.
 - Suspected something wrong in gas.
 - In July, changed 10 m of gas pipe. Was nylon, now aluminum coated pipe.
 - No visible change. Now suspect a leakage in some pipe connector, or O2 in the Argon bottle

drift_speed_cmmus_*timeslope_gain*0.04:times {Timecut&&Ngood>200}



green: e- capture determined from resolution vs z
 red e- capture determined from charge vs z

attachment_rate:f_OXYGEN





Attachment $\sim 1/80 \text{ cm}^{-1} \leftrightarrow f_{\text{O}_2} \sim 3\text{E}-5$

This is expected from atmosphere due to a leak of $\sim 1.5 \text{ ml/hr}$

Test with a gas sniffer

- Use a gas sniffer to detect any Argon leakage
- Several leaking zones have been spotted where Oxygen may flow in



- Need to open in clean room to fix the most important leak
- This should happen in a few weeks, as there are some plans to change the module with a new prototype (designed to get 100% of the 1728 channels responsive)

- Detector alignment improved
 - There were too many degrees of freedom
 - Things are stable now
- Data quality
 - Gas quality:
 - Evidence for leakage in TPC
 - TPC need to be fixed.

Support