The MEG2 Drift Chamber Experience

F. Grancagnolo INFN Lecce, IHEP, November 18, 2019

 $t_{e} = t_{\gamma}$ $E_{e} = E_{\gamma} = 52.8 \text{ MeV}$ $\theta_{e\gamma} = 180^{\circ}$



Best world limit (MEG): *Eur.Phys.J.* C76 (2016) 434 $BR(\mu^+ \rightarrow e^+ \gamma) < 4.2 \times 10^{-13} @ 90\% CL$

General Layout

ī.



needing novel approaches to the wiring procedures

Wire Support



wire frames

support structure

End-plates numerically machined from solid Al and Au plated



The wire PCB's

The wire PCBs are made of 400 μm thick FR4 board with 35 μm gold plated copper traces.

All wire pads are oriented along the stereo angle

US and DS wire PCB are coupled together in a single FR4 board for a precise alignment during the wiring procedure





The wiring robot



accomplishes wire:

- positioning,
- tensioning,
- soldering,
- layer extraction

wire spool e.m. brake torquemeter

- wire tension measurement
- IR laser soldering
- wire positioning camera
 - winding drum
- wire layer extraction system

Stacking the wire layers





The multi-wire layer is placed next to the end plates for the engagement procedure and stretched between two spokes on one side and the corresponding ones on the other side.



During the assembly phase, the endplates are placed at a shorter distance than nominal to avoid stressing the wire

This procedure is repeated for each of the 12 sectors. After completing a layer, a survey is performed on the radial position. Spacers, to separate the

adjacent layers, are built accordingly and are pressed and glued in position. The multi-wire layer placing procedure is repeated for all 10 layers



A short history of wire problems

A short history of wire related problems

- March 2016 (wiring started Nov. 2015)
 many field wires mounted on the chamber, found broken due to unsuspected extreme sensitivity to humidity. Detailed analysis revealed a corrosion pattern.
 September 2016 restarted wiring and assembly from scratch
- 2. October 2016 human error caused a few wire breakings. Procedures revised and wiring and assembly resumed in December 2016.
- 3. July/August 2017 14 wires found broken inside the chamber. Removed. Improved environmental conditions and air dryness. Assembly resumed in September 2017. Decided to limit wiring to 9 layers with a slightly de-tensioned (-1 mm) chamber to avoid excessive stress to weak wires.
- 4. Wiring and assembly completed in December 2017.
- 5. October 2018, found a broken cathode during operation. Again due to earlier initiated corrosion.
- After partial engineering run in Nov. 2018, extract chamber from COBRA. Chamber reopened and extra-tensioned (+1.2 mm) to eliminate wires with corrosion process in progress. 49 more wires eliminated. All showed clear signs of corrosion. Chamber kept under extremely low humidity for the whole summer at extra-tension. No sign of further damage ever since. Tension partly released. Chamber closed.

A short history of wire problems

A short history of wire related

- 1. March 2016 (wiring start many field wires mount to humidity. Detailed ar September 2016 restar
- 2. October 2016 human eri Procedures revised and
- 3. July/August 2017 14 win conditions and air dryne with a slightly de-tensio
- 4. Wiring and assembly co
- 5. October 2018, found a b
- After partial engineering extra-tensioned (+1.2 n All showed clear signs at extra-tension. No sig



A short history of wire problems

A short history of wire related problems

- March 2016 (wiring started Nov. 2015)
 many field wires mounted on the chamber, found broken due to unsuspected extreme sensitivity to humidity. Detailed analysis revealed a corrosion pattern.
 September 2016 restarted wiring and assembly from scratch
- 2. October 2016 human error caused a few wire breakings. Procedures revised and wiring and assembly resumed in December 2016.
- 3. July/August 2017 14 wires found broken inside the chamber. Removed. Improved environmental conditions and air dryness. Assembly resumed in September 2017. Decided to limit wiring to 9 layers with a slightly de-tensioned (-1 mm) chamber to avoid excessive stress to weak wires.
- 4. Wiring and assembly completed in December 2017.
- 5. October 2018, found a broken cathode during operation. Again due to earlier initiated corrosion.
- After partial engineering run in Nov. 2018, extract chamber from COBRA. Chamber reopened and extra-tensioned (+1.2 mm) to eliminate wires with corrosion process in progress. 49 more wires eliminated. All showed clear signs of corrosion. Chamber kept under extremely low humidity for the whole summer at extra-tension. No sign of further damage ever since. Tension partly released. Chamber closed.

Wiring completed



Closing with two half cylinder carbon fiber shells





1 0

Measured geometrical tolerances



End-flanges removal: turnbuckles are removed and the chamber is disengaged from the support structure on the granite table used for wiring



Central shaft removal: turnbuckles are removed and the chamber is disengaged from the support structure on the granite table used for wiring

Innner 20 µm mylar foil inserted





Distance between the average endplate planes:1992.840 mm (+4.840 mm)Endplates planarity: 40 μm (US), 30 μm (DS)Parallelism between the average endplateplanes: 80 μmRelative azimuthal tilt of endplates:0.001°Radial deformation of endplates:60 μm (US), 55 μm (DS)1

Gas sealing and ground connection



ThreeBond





Stycast

All the 40/50 μm cathode wires are grounded together

all the inner guard wires (HV1) all the outer guard wires (HV2) are connected together

FE cards holders and tube cooler holders

A weak point

Discovered a critical aspect responsible for a weakness of some drift cells between two adjacent sectors

Deformations O(≈100 µm) have been spotted, sufficient to cause this problem





Packing and shipping to PSI



mounting end-plates extensions wrapping in controlled atmosphere



mounting in shipping structure



second wrapping



thermal shield

End-plates dressing: cooling and sensors



The water cooling system to cool the electronics and a dry air system to keep the humidity low inside the extension



24 temperature sensors directly connected to the FE holders

4 humidity sensors

4 PT1000 (cooling tubes and endplates)

have been mounted to control the temperature and humidity inside the extensions

Also sensors to measure the gas inlet temperature

End-plates dressing: front end cards



Mount all DS and US FE cards (532)

Insertion in COBRA magnet





Final cabling





Commissioning

Missing wires effect



> CDCH has a mesh of criss-crossing cathode wires between anode planes

- > Used Garfield and ANSYS to simulate the electric field in a $6 \times 6 \text{ mm}^2$ representative drift cell + $B_z = 1.26 \text{ T}$
- > The aim is to study the effect of a missing wire on isochrones and so on positron recostruction
 - The effect of the missing cells has been simulated in high statistic MC runs
 - 100k signal events, and 1000k background
 - removed 21 wires on L9 and 10 wires on L8)
 - The number of missing cells is so far only 0.8%

missing cell effect

Positron efficiency in cascade

| | ε(Acceptance) % | ε(DCH fake) % | ε(prop.cut) % | ε(tail cuts) % | ε(matching) % | ε(SPX fake) % | ε (time cut) % ±0.2 |
|--------------|--------------------|------------------|------------------|-------------------|------------------|------------------|------------------------|
| standard | 91.3 | 87.6 | 81.5 | 67.1 | 65.4 | 65.4 | 63.4 |
| usable wires | 91.3 | 87.4 | 81.1 | 66.3 | 64.6 | 64.5 | 62.6 |

Resolutions

| | σθ/RMSθ (mrad) ±0.03 | σφ /RMSφ (mrad) ±0.03 | σp/RMSp (keV) ±0.4 | σz/RMSz (mm) ±0.006 | σy/RMSy (mm) ±0.006 |
|--------------|-------------------------|--------------------------|-----------------------|------------------------|------------------------|
| standard | 6.217/6.876 | 5.766 /6.514 | 87.5/103.6 | 1.379/1.590 | 0.728/0.828 |
| usable wires | 6.221/6.879 +0.04% | 5.822/6.585 +1% | 88.0/103.9 +0.3% | 1.384/1.601 | 0.736/0.837 |

19



Expected Performance

MEG drift chamber

MEG2 drift chamber

Single hit resolution

| • | σ_{R} (mm) | .250 (core) | .300 (RMS) | .100 (core) | .130 (RMS) |
|---|-----------------------|-------------|------------|-------------|------------|
| • | $\sigma_{\rm Z}$ (mm) | .700 (core) | 1000 (RMS) | .700 (core) | .900 (RMS) |

Track resolution

| • σ (p) | 310 KeV (core) | 115 KeV (core) | |
|--------------------------|---|----------------|--|
| σ(φ) | 7. mrad (at $\phi = 0$, 10 mrad aver.) | 5.3 mrad | |
| σ(θ) | 11. mrad | 4.8 mrad | |
| • σ(Y) | 1.3 mm | 1.2 mm | |
| • σ(Z) | 3.0 mm | 0.7 mm | |

TC – DC reconstruction

• DC-TC matching eff. 45 %

88%