

# Survey of the Cavity

Stefano Gramigna on Behalf of the Working Group 2024/09/09 BESIII Upgrade Meeting




 $d_n$  = Diameter at position n  $e_n$  = Ellipticity at position n L = Distance between anchoring points

l = Internal length of the cavity (considering the new ring)



 $d_n$  = Diameter at position n  $e_n$  = Ellipticity at position n L = Distance between anchoring points

l = Internal length of the cavity (considering the new ring)



## Relative Measurements on the MDC Flanges


- Parallelism of the MDC flanges
- Perpendicularity of the MDC flanges with respect to the longitudinal axis of the cavity

### Considerations

- Measurements should be performed after installing the separation cylinder and test-mounting the EAST flange
- Measurements should be double-checked with conventional tools (rulers, calipers) wherever possible

# Inquiry on the Shielding

### Shielding Plate Proposal



# Last Meeting's Indications

- Shielding to be installed before the positioning of the beam pipe's central section
- No windows are necessary on the shielding plates

#### **ISSUE**

The shielding plate prevents access to the pusher screws for the beam pipe's positioning!

#### **SOLUTIONS**

Install the shielding plates after positioning the central section of the beam pipe (RECOMMENDED)

OR

Make windows for accessing the pusher screws (reduces shielding effectiveness, complicates operations)

# Inquiry on Cabling along the Beam Pipe

# Which is the Correct BESIII Closing Order?

A B

1. Reinsert ECAL endcap

1. Reinsert ECAL endcap

2. Close doors

OR

2. Reinsert SCQ

3. Reinsert SCQ

3. Close doors

# Thanks for your attention