Progress and Plan

Mingyi Dong

2024.9.23


Progress in the experimental hall last week

	Planned tasks last week	Time needed (day)	person in charge	Status
1	Pull out the long rail	1	Facilities Operation group (Jing Xiaoping)	done
2	Gas sealing and leakage checking (before and after changing MDC working gas)	4	Mingyi Dong, Jing Dong	done
3	Laser measurement of MDC 1 position after removing the iMDC		Lingling Men	Move to this week
4	Check and recover the step part of MDC	2	Mingyi Dong	done
5	Replace the dead preamps of MDC step part	2-3	Yunhua Sun	Finished the tests of the preamp


Gas sealing

• September 18

- For the convenience of gas sealing operation and laser measurement, pulled out the long rail, and removed the small leg on the east side
- Removed the positioning targets on the west flange2
- Trial installation of the new east flange2. It is ok.
- Stopped gas flow, sealed CF cylinder and the screws/holes on the west flange2 with epoxy









Leakage check

• September 19

- Check leakage with Ar in drift chamber. No big leakage was found
- Re-sealed the screws for fixing the CF cylinder on west side
- Trial installation of the new east flange2. The flange can not be installed after glued the CF cylinder. Need modification.
- Trial installation of the new shielding plates for step part
- Changed Ar with MDC operating gas (He/C3H8)






Restoration of the step part

- September 20
 - Installed the grounding boards of the first step of MDC on east side
 - Check leakage with gas mixture of He/C3H8 in drift chamber. Small leakage was found on the west fange2








Restoration of the step part

September 21

- Tested the wire tension again. After the wire tension test, restored the connection of the signal cables for the sense wires
- Re-sealed the positioning target holes on west flange2
- Completed the testing of the preamp boards to replace the dead preamps of the MDC







Gas sealing and leakage check

- September 22
 - Re-sealed the positioning target holes on west flange2
 - Re-sealed the CF cylinder on east side







Plan for next week

	Tasks	Time needed (day)	person in charge
1	Replace the dead preamps of MDC step part	4	Sun Yunhua
2	leakage checking and sealing	2	Mingyi Dong, Jing Dong
3	Laser measurement of MDC position after removing the iMDC	1	Lingling Men
4	High voltage training and cosmic-ray tests	3	Mingyi Dong
5	Recover the shielding plate	2	Mingyi Dong

Backup

Schedule (may be updated each week)

No.	tasks	Duration (day)	Start time and stop time	Sub-system involved
1	Removal of equipment of machine		July 1- Aug. 6	Utility, Small angle lum. Detector and ZDD, Beam pipe, slow control
2	Pull-out of EEMC			Utility, EMC, TOF, MDC, MUC
3	Removal of inner chamber (Operate simultaneously on both sides)	51	Aug. 7- Sep.7 Sep.8- Sep. 28	MDC, MDC electronics, Gas, Mechanics, Laser Alignment group, Trigger, DAQ, Slow control
4	Installation of CGEM	44	Sep.29- Nov. 11	CGEM group, MDC, MDC electronics, Gas, Mechanics, Laser Alignment group, Trigger, DAQ, Slow control
5	Recover EEMC		Nov. 12-Dec.30	Utility, EMC, TOF, MDC, MUC
6	Recover equipment of machine			Utility, Small angle lum. Detector, ZDD, Beam pipe, slow control,
total		180 days	July 1- Dec.30	

Key tasks before extraction of iMDC and installation of CGEM

- CGEM Mock-up insertion test (Done, successful)
- Laser alignment preparation (Done)
- Extraction of the inner MDC is considered to be the most critical point. Continue inner chamber extraction test (Done, passed the review)

- Continue CGEM cosmic-ray test to gain more experience with the full detector
- CGEM integrated and tested with BESIII DAQ, trigger, and slow control