
Time evaluation of temperature layer15 chip2 channel20



- Many channels have several temperature "curves" during one run
 - This is true for many runs
 - Temperature sensor might NOT be calibrated
- Temperature sensors also have many "curves"
 - Different situation from cosmic ray test
 - Problem at RawtoRoot or DAQ



20210123_1040_cosmicRayTst.root

