

Beta source test for TaichuPix3 FLEX BOARD

Tianya Wu wuty@ihep.ac.cn 2023.02.23






Test for U10 on V1P4-B




- ITHR =224;
- Power Status: 12V/0.385A;
- Readout phase: 0.356-0.385A
- CLK=15.625MHz



30mins later

Power Status: 12V/0.389A;

Readout phase: 0.359-0.374-0.389A





A slightly current difference, 4 mA increasing, this may from the running temperature, since no cooling here. 1 hours later, it goes to 0.393A






Try to fix via configuration







- Only reset make sense to recover the readout data.
- Reset will clean timesatamp; configuration on pixel array; buffers; serializer interface.





Thanks for your attention!

